

CONCRETE CLOTH™ DITCH LINING CASE STUDIES

01.06.10 Case Study : Cholsey Case Study



On the 1st June 2010, Dyer and Butler started work to repair a drainage ditch which was at risk of overflowing onto an adjacent public road. Network Rail specified Concrete Cloth for the ditch which ran for 50 metres next to Cholsey Train Station near Wallingford in Oxfordshire.

"Using Concrete Cloth at this site had great benefits over conventional methods, with speed of delivery of works and negligible disruption to the local public and road users"

**Graham Spence, Senior Site Agent
Dyer & Butler**



Proudly Distributed By:

ACTIVE
Trade Solutions
"The Tradesman's Choice"

1300 2 ACTIVE 1300 222 848

56 Enterprise Street Bundaberg QLD 4670

Email: sales@activetradesolutions.com

Web: www.activetradesolutions.com